

FCA


DURO DYNE®

FLEXIBLE CONNECTOR ADHESIVE

THE SENSIBLE SOLUTION TO MAKING YOUR FLEXIBLE DUCT CONNECTOR SEAM!

Follow these simple steps to join your flexible duct connector together.

1. Cut away 1-1/2" of metal from one side of your connector, leaving a 1-1/2" tongue of fabric. (Fig. 1)
2. Overlap connector ends 1-1/2" and screw or weld together. (Fig. 2)
3. Apply one or two lines of FCA, sparingly, on fabric, under tongue. (Fig. 3)
4. Press tongue down on adhesive. Rub gently and hold for 10 seconds. (Fig. 3)
5. For an airtight connection, apply duct sealer over metal joint.



Available in 1 oz. bottles from your local Duro Dyne Distributor.

Store in a cool, dry place.

Shelf Life: 3-6 months

Not recommended for Teflon.

FCA-Flexible Duct Connector Adhesive

Item#	Code	Description	Quantity
5090	FCA	Flexmastic Adhesive	1 Per Ctn.

Duro Dyne East Division, Bay Shore, NY 631-249-9000 Fax: 631-249-8346
Duro Dyne Midwest Division, Fairfield, OH 513-870-6000 Fax: 513-870-6005
Duro Dyne West Division, Santa Fe Springs, CA 562-926-1774 Fax: 562-926-5778
Duro Dyne Canada, Lachine, Quebec, Canada 514-422-9760 Fax: 514-636-0328
www.durodyne.com E-mail: durodyne@durodyne.com

DURO DYNE®

© Duro Dyne Corp.
Printed in USA 11/15
FCA0599